

G0xin – License

Introduction

- 1) **Disclaimer:** It is assumed that you have read, understood and accepted the terms & conditions listed in the document <http://www.g00.in/introduction.pdf>.
- 2) **Download:** Please download and install the **latest version** of the software from <http://www.g00.in/g0xin.msi> . Do not use the older version of the software.
- 3) **Get Started:** Click on the link => <http://www.g00.in/go.pdf> to get an overview of the software. Refer to the stepwise procedure mentioned in this document to install the software and start using it.
- 4) **Signature:** Copy the attached file **signature.dat** in the folder **C:\g0xin**. Take its backup now.
- 5) **Password:** You will find it in the text file **Srno***.txt**, attached with this message. It contains **42 digits** and uses only numbers from **0-9**. You have to type it while confirming a layout. Take its backup now.
- 6) **Post-processor:** Copy your own post-processor file **processor.c2d** in the folder **C:\g0xin**. Take its backup now. (Sample file is available in **C:\g0xin\samples\trial\processor.c2d**.)
- 7) **Cutting Parameters:** Copy your cutting parameters file **materials.csv** in the folder **C:\g0xin**. Take its backup now. (Sample file is available at **C:\g0xin\samples\trial\materials.csv**.)
- 8) **Help:** For detailed description, select the command **Help => Index** in the software.

Data Management

- **Plan:** Plan files are automatically created, updated and removed in your JOB folder.
- **Report:** All the report files are automatically saved in HISTORY folder, when you confirm a layout.
- **CNC Code:** CNC Code file is automatically written in the CODE folder, when you confirm a layout. **Do not remove or edit any code file for 12 months after its creation.**
- **Offcut:** Offcut files, if created, are automatically saved in OFFCUT folder, when you confirm a layout.
- **Bill of Materials:** You can create the bill of materials offline from your own database and add all the parts automatically, while creating a new job. For details, check the file **C:\g0xin\bom.csv**.
- **Inventory:** You can create the inventory offline from your own database and add all the raw material sheets automatically, while creating a new job. For details, check the file **C:\g0xin\inv.csv**.
- **Macro:** You can create simple part drawings (like, rectangle, circle, etc.) directly using macros, without creating their part drawing files.

Reference Documents

- <http://www.g00.in/introduction.pdf>
- <http://www.g00.in/go.pdf>
- <http://www.g00.in/step1.pdf>
- <http://www.g00.in/flowchart.pdf>
- <http://www.g00.in/doc/movies.pdf>
- <http://www.g00.in/doc/materials.pdf>
- <http://www.g00.in/doc/errors.pdf>

E-mail Attachments

- **Signature:** Copy the attached file **signature.dat** in the folder **C:\g0xin**. Take its backup now.
- **Password:** You will find it in the text file **Srno***.txt**, attached with this message. It contains **42 digits** and uses only numbers from **0-9**. You have to type it while confirming a layout. Take its backup now.